



# 2014 Oso Slide

The last 45,000 Years:

*Our*  
Observations and Current Thoughts  
On The

Geology and Failure Development/Causes

Part 1: Laying the Groundwork



# What, When, and Where:

Saturday, March 22<sup>nd</sup>, 2014  
around 10:37AM

Lasted Approximately 2 Minutes


Largest Slide Disaster in US History

Killed 43 People


\$ 71.5 M in Settlements:

State \$ 60 M, Grandy Lake \$ 11.5 M, SnoCo \$ 0

Scale: 1: 7,500,000







Skagit

Cultus Mountains

Sauk


NF Stillaguamish

Oso

Glacier Peak











# 2013 LiDAR Hillshade





# 2014 LiDAR Hillshade






# 2012 Aerial Photo




0 750 1500 ft





**3/24/14 Aerial Photo**







<https://www.youtube.com/watch?v=UUFByAwcGs0&t=14s>



22-MAR-2014  
11:22:33

FLIR  
SYSTEMS



2:15 / 21:26






22-MAR-2014  
11:25:57

FLIR  
SYSTEMS



▶ ⏪ 🔊 5:39 / 21:26





22-MAR-2014  
11:31:15

FLIR  
SYSTEMS



10:58 / 21:26





22-MAR-2014  
11:27:48

FLIR  
SYSTEMS



7:31 / 21:26






22-MAR-2014  
11:30:22

FLIR  
SYSTEMS



▶ ⏩ 🔊 10:05 / 21:26





# Why Did This Happen?

The day after the event, some journalists (in newspapers, radio, and TV) started implying that this disaster was related at least in part to an 8.5-acre clearcut performed 9 years prior to the event.

The regulatory bodies (DNR, Board of Forestry) have publicly reviewed and changed their guidelines for slope stability assessments for timber harvest in the wake of the disaster. This is clearly an attempt to do SOMETHING. The public has perceived this as a tacit acknowledgement (implication) that forestry issues were indeed a significant part of the problem.




# What Everybody “Knows”:

- Ice ages happened.
- Glaciers deposited stuff.
- Glaciers melted.
- Rivers eroded stuff.
- Landslides happened.
- **Loggers came.**
- More landslides happened.
- **Loggers came again.**
- **Oso happened (because of the logging...?)**








**So First, Let's Look at that CLEARCUT**

**2004 Harvest Boundary**



**+/- 8.5 Acres**

**2014 Head Scarp**


**2012 Snohomish County Aerial**













**2004 Harvest Boundary**

**3/24/2014 LiDAR Hillshade**









# “Conventional Wisdom” Based on Assumptions:

1. Groundwater Flow to SE (Toward Slide)




2. Precipitation on Bench Recharges Entire Soil Column

2013 LiDAR Hillshade






# The State's Experts Needed Actual Information





# Actual Groundwater Flow to ENE and ESE:






← W

Photo 3-24-14, Courtesy King County Sheriff

E →

**Aquitard**





3/25/14 Photo Courtesy Snohomish County

**Eastern Head Scarp**

**Aquitard**

**Even Only 3 Days After the Slide, Just Minor Seeps**





3/25/14 Photo Courtesy Snohomish County


Western Head Scarp

Aquitard





# Several Lines of Evidence Eliminate 2004 Clearcut as Cause




1. Groundwater Flow Direction Beneath Harvest Area is Away From Slide Area
2. Aquitard Prevents Precipitation Falling on Clearcut from Reaching Critical Aquifer
3. Piezometers Indicate No Direct Response of Groundwater Levels to Precipitation.
4. Rain Gauge Study (28 Gauges, Dr. Skaugset) Indicates no Significant Throughfall Difference Between 9-Year Old Reprod and 27- and 80-Year-Old Stands at Site.
5. 440-acre Clearcut in 1988 did not result in Oso-type Event.



# What the Chronology Should be:

- Ice ages happened.
- Glaciers deposited stuff.
- Glaciers melted
- **Landslides happened**
- Rivers eroded stuff
- **More landslides happened**
- Loggers came.
- **Houses were built**
- **More landslides happened**
- **More houses were built**
- **Oso happened**






# Geologic Evidence Origin and Early History of the Deposits

How 600+ Feet of Ice-Age Soil arrived at this Spot Between 45,000 and 13,000 Years Ago










NW

Section 7 Extended

SE





**As usual, the devil is in the details!  
Maybe Illumination Also?**







Ice Sheets 24,000 to 13,000 YBP:

A Complicated  
BIG PICTURE  
(of Ice Flow Directions)

How do we know this???









Ice Flow Cues

0 1000 2000 3000 ft









0 1000 2000 3000 ft























# Whitman Bench is no Accident!

- Whitman Bench is located at this spot due to complex interaction of several different glaciers or glacial lobes.
- All glacial lobes were contributing sediment to this area
- Due to UNUSUAL converging ice flow directions, ice flow across the site was minor.
- This resulted in minimal glacial erosion, preserving significant portions of the uncemented sediments comprising the 600'-high benches.




# Whitman Bench Stratigraphy (GEER, 7/22/14)



Overview of Slope Movement from SE  
From GEER Report 7/22/14

If only it were THAT SIMPLE!











# Whitman Bench Stratigraphy (Our Version)

UNIT	THICKNESS	UPPER CONTACT ELEV.
<b>RECESSIONAL OUTWASH (deposited during deglaciation):</b> Sand and Gravel (Includes Basal Silt)	67-134	Surface (832 – 892)
<b>TILL COMPLEX:</b> Discontinuous Lodgment Till Deformation Till Flow Till In some borings contains sections of stratified Silt, Sand, and Gravel	0 – 130'+	733.5 – 771'
<b>ADVANCE OUTWASH (deposited prior to the ice covering the site)</b> Mostly dark gray Silt/Silty Sand in thick Eastern Portion of Head-scarp Gravel Delta with Flow Tills in Central Portion of Head-scarp Ice-Contact Coarse Sand/Pebble Delta in West Portion of Head-scarp	7 – 188'	660 – 688'
<b>BEAR LAKE RHYTHMITES</b> Rhythmically Bedded (1/16" – ½") Silt/Clay Couplets	75 – 300'+	400 – 653.5'
<b>BEAR LAKE SAND</b> Very fine- to Coarse-grained, Poorly Graded Sand Occasional Silt/Clay Rhythmite Interbeds	90+'	313 – 325'



# Bear Lake Sand

Next Photos







**Next Photo**









**Slide Deposit (Transported Recessional Outwash)**

**Failure Surface**

**Horizontal Top-set Beds**

**Fore-set Beds Dipping NW**

**Bear Lake Sand (Oldest Unit at the Site)**







**Transported Recessional Outwash  
(Slide Deposit)**

**Failure Surface**

**Bear Lake Sand**





**Bear Lake Sand**

**Over-consolidated, Sheared Silt/Clay Rhythmite Interbed**





Bear Lake Sand

FB-09-15  
P. 18  
Depth. 134-135.5  
Re. 21-41-44 (85)  
Rec.  
Ret.





# Bear Lake Sand Summary:

- 90+ Feet of Poorly Graded Sand, Very Fine- to Coarse-Grained
- Foreset- and Topset-Bedded
- Occasional Silt/Clay Rhythmite Interbeds
- Occasional Drop Stones
- Origin: Deltaic Deposit in Lake





## Moraine-Dammed Lake?

### Problems:

1. NF Stillaguamish is a powerful river and would have eroded a moraine dam relatively fast.
2. Silt/Clay Interbeds indicate fluctuating lake level during Bear Lake Sand time.





## Landslide-Dammed Lake?

Problems:

1. NF Valley would have been +/- 3 miles wide.
2. Fluctuating lake level can't be explained.





## Ice-Dammed Lake?

**Option A:** Dammed by Puget Lobe Arm extending into NF Valley


**Problem:** If Bear Lake Sand is +/- 45,000 yrs old, there was no Puget Lobe

**Option B:** Dammed by Local Glacier.

**Problem:** None?



# Bear Lake Sand Deposition



Rock Knob Anchor

Rollins

Deltas

N.F. Lobe

White Horse Lobe

0 1 2 3 miles



NW


Section 7 Extended

SE


### Bear Lake Sand Deposition (Before +/- 40,000 YBP)

White Horse Lobe

Bear Lake Sand










# Bear Lake Rhythmites

Next Photos








**Slide Deposit**

**Bear Lake Rhythmites**

**Bear Lake Sand**






**Failure Surface**

**Slide Deposit**

**Bear Lake Rhythmites**

**Bear Lake Sand**





Failure Surface


Bear Lake Rhythmites  
(Lowermost Portion)



**Bear Lake Rhythmites  
Standard Penetration Test, EB-07, 78-80'**







**Bear Lake Rhythmites  
Dames and Moore Sampler (2.5" ID)**

**Note Thickness of Individual Laminae Smaller than Color Banding**



# Bear Lake Rhythmite Deposition

Snout Crosses Valley  
Spillway Elevation Rises




Lake Level Rises, Delta Deposition Moves Upstream  
Site Receives Suspended Load Only

North Fork  
Lobe

Whitehorse Lobe

0 1 2 3 miles






NW

Section 7 Extended

SE



### Bear Lake Rhythmite Deposition (+/- 40,000 to +/- 20,000 YBP?)





# Advance Outwash

Next Photo








**Advance Outwash Sandy Silt  
Failing over BLR  
East Margin, April 2016**






Next Photo





Advance Outwash  
Laminated VFG Sand w/Silt  
in Failure Block near Center of Slide





Advance Outwash  
Laminated Sand





# Advance Outwash Center of Headscarp

+/-130' Recessional Outwash

Till

Till







Recessional Outwash

Till


Sand & Gravel

Advance Outwash  
Central Head-scarp

Flow Till

Fore-set Beds Dip  
Into Head-scarp (NW)





Next Photo







Sand Dips to NE

Advance Outwash  
Ice-Contact Stratified Drift  
(Sand & Gravel)  
West Margin

Note Offset Gravel Beds  
And Light-Colored Cobbles




# Advance Outwash Summary

- Grainsize Highly Variable from Sandy Silt to Sandy Gravel
- Grainsize Location-dependent. Generally Finer-grained in East.
- Coarser Portions Fore-set Bedded.
- Portions Demonstrably Deposited in Contact with the Glacier.
- Deltaic and Lacustrine Origin





# Advance Outwash





NW

Section 7 Extended

SE

# Advance Outwash Deposition (+/- 20,000 - 18,000)


Rollins Ck. Lobe

North Fork Lobe (to E)  
Puget Sound Lobe (to W)?


White Horse Lobe

Bear Lake Rhythmites (Silt/Clay)

Bear Lake Sand







Next Photo

Till







## Lodgment Till Block in Talus Beneath Head-scarp

Note Subdued Darker Cobble/Boulder Colors





Next Photo








Skadulgwas Peak

Lodgment and Flow Till in Eastern Headscarp  
(100'+)

Head-scarp Collapse  
Till Blocks

CME 850 & Excavator










Lodgment Till Core in EB-02



C-15  
122'









Flame Structures in Deformation Till in  
Bear Lake Rhythmites  
EB-07 (64-66')



A photograph of a geological outcrop showing distinct horizontal layers of rock. The top layer is a light-colored, sandy material. Below it is a darker, more layered section. A red arrow points from a red object (possibly a pen or pencil) on a ledge in the foreground to a specific layer in the middle of the outcrop. The foreground is a rocky, pebbly area.


**Bear Lake Sand**

**Over-consolidated, Sheared Silt/Clay Rhythmite Interbed. Deformation Till**



# “Kissing Glaciers” Or “Glacial Gridlock”

Deposition at the Site All But Ceases  
Some Glacial Scour of Sediments Starts  
In Central Portion of Valley




Rollins

Puget Lobe

The Melting Pot

North Fork Lobe

Whitehorse Lobe





NW

Section 7 Extended

SE


# Initial Lodgment Till Deposition at Site (+/-18,000 YBP?)

Rollins Ck. Lobe

North Fork Lobe  
Puget Lobe?


White Horse Lobe

Bear Lake Rhythmites (silt, clay)  
Bear Lake Sand





# Glacial Maximum (18K to 14K Years Ago): Age of Nunataks






NW

# Glacial Maximum (+/-18,000 YBP?)

SE


Combined (Confluent) Glaciers

Rollins Ck., North Fork, Puget, & White Horse Lobes






# 1<sup>st</sup> Recessional Phase: Collapse of Local Ice Caps










NW

Section 7 Extended


SE

# North Cascades Ice Sheet Collapse +/-18,000 - 14,000 YBP





2nd Recessional Phase:  
Outwash Over Dead Ice and in Low Areas.





NW

Section 7 Extended

SE

# Puget Lobe Recession (+/- 13,000 YBP)

Rollins Ck. Lobe


Puget Lobe Remnants

White Horse Lobe

Bear Lake

Clay

Bear





# Recessional Outwash


Mostly Tan to Orange  
Sand with Light-Colored  
Pebbles and Cobbles





# Recessional Outwash

Most Cobbles Light-colored:  
Sourced in BC





# Recessional Outwash

Often Covered in Forest Floor





# Recessional Outwash

Extended Forest Floor and Transported Alders





# Recessional Outwash in Central Head-scarp






Hopefully,  
You Now Have Some Understanding  
of the Origin and Characteristics  
of the Sediments.






# WHY DID YOU NEED TO KNOW THIS?

- This information provides the framework for the how and why of the Oso slide.
  - Without this knowledge, there is no basis for opinions regarding reasons for "Oso."
  - If you cannot determine reasons, you cannot know what "went wrong".
  - If you don't know what went wrong,
    - You cannot know if, where, and why it might happen again.
    - You cannot develop effective guidelines for this and similar sites.
    - You cannot assign or refute blame as appropriate.
- 



## IN PART 2 WE WILL:

- Find out How we Arrived at March 22, 2014 (and see some of the evidence).
  - Find out What Happened in the 2 Minutes it Took the Oso Slide to Move a Mile, Along with Some of the Evidence for this Interpretation.
  - Find out What's Happened Since.
  - Discuss Ramifications?
- 
- A decorative graphic consisting of several parallel white lines of varying lengths, slanted diagonally from the bottom right towards the top right, set against a blue background.



**PART 2:  
And Now we Diverge**



**From Another Dominant Paradigm**



# The Dominant Paradigm

## BACKGROUND

When the Cordilleran ice sheet advanced southward into the Puget Sound ~17,500 yr ago, it dammed rivers flowing west from the Cascade Mountains (Porter and Swanson, 1998), filling the North Fork Stillaguamish River (NFSR) valley with 200 m of glacial sediment. Geologic mapping indicates that numerous landslides have occurred in this sediment (Dragovich et al., 2003), which is characterized by low-permeability glaciolacustrine clays overlain by sandy advance outwash, till, and gravelly recessional outwash (Keaton et al., 2014; Riemer et al., 2015). Similar stratigraphy is prevalent in the region and is well known to be landslide prone during and soon after high-intensity or long-duration precipitation (Chleborad, 2000; Coe et al., 2004).

Following ice retreat ~16.4 k.y. ago (Porter and Swanson, 1998; Beechie et al., 2001), the NFSR began incising rapidly into these mechanically weak glacial deposits, creating the modern valley relief and setting the stage for long-standing slope instability in the area.

Geology, published online on 22 December 2015 as doi:10.1130/G37267.1

Surface roughness dating of long-runout landslides near Oso, Washington (USA), reveals persistent postglacial hillslope instability

Sean R. LaHusen<sup>1</sup>, Alison R. Duvall<sup>1</sup>, Adam M. Booth<sup>2</sup>, and David R. Montgomery<sup>1</sup>

<sup>1</sup>Department of Earth and Space Sciences, University of Washington, Box 351310, Seattle, Washington 98195, USA

<sup>2</sup>Department of Geology, Portland State University, 1721 SW Broadway, Portland, Oregon, 97201 USA







Figure 3. A: Lidar bare-earth imagery of the study area, showing all mapped landslides colored by estimated age. Landslides are binned into four age classes (7 class A, 3 class B, 10 class C, and 5 class D; see text) based on estimated age from the surface roughness-age regression. Predicted age classes agree well with crosscutting relationships between landslides. cal yr B.P.—years before present (present = 1950). B: Blow-up map showing inferred river position (dashed line) prior to the Rowan landslide (Washington State, USA) ca. 500 <sup>14</sup>C yr B.P., based on erosional contact on an older landslide deposit. The current river position (solid line) suggests that the active channel was displaced at least 600 m when the Rowan landslide occurred.




A grayscale topographic map showing a wide valley with a river winding through it. The terrain is rugged with many smaller ridges and valleys. A scale bar at the bottom of the map is marked from 0 to 10 miles in increments of 1 mile.

**1 Million Cubic Yards of Material Per Year Would Have to be Eroded Just from This 10-Mile Section of the NF Valley for 13,000 Years to Create the Valley.**

A close-up view of a topographic map showing a valley with a river. The terrain is highly detailed, showing the intricate patterns of erosion and the surrounding hills.

**But wait, There's More!**






This Means 5 – 10 Million Cubic Yards per Year Must be Removed from 10-Mile Stretch (from +/- 13,000 to 11,692 YBP).

But There is Another Way!

Figure 3. A: Lidar bare-earth imagery of the study area, showing all mapped landslides colored by estimated age. Landslides are binned into four age classes (7 class A, 3 class B, 10 class C, and 5 class D; see text) based on estimated age from the surface roughness-age regression. Predicted age classes agree well with crosscutting relationships between landslides. Calibrated Carbon Age (YBP)—years before present (present = 1950). B: Blow-up map showing inferred river position (dashed line) prior to the Rowan landslide (Washington State, USA) ca. 500 <sup>14</sup>C yr B.P., based on erosional contact on an older landslide deposit. The current river position (solid line) suggests that the active channel was displaced at least 600 m when the Rowan landslide occurred.






Location of Photo on Next Slide







**Horizontal Outwash**

**Less Rotated Outwash**

**Rotated Outwash**

**Rotated Till**

**Till Block Jumble/Dipping & Horizontal Outwash  
Conundrum**



NW

Section 7 Extended

SE

# Puget Lobe Recession (+/- 13,000 YBP)

Rollins Ck. Lobe


Puget Lobe Remnants

White Horse Lobe

Bear Lake

Bear

Clay







Section 7b

— 2003 — 2006 — 2013 — 2014

# Prior to First Kame Terrace Failure P1 (+/- 13,500 YBP)







(a)



(b)








Section

2003


2006

# P1: First Kame Terrace Failure (+/- 13,500 YBP)

## Whitman Bench







**Horizontal Outwash**

**Less Rotated Outwash**

**Rotated Outwash**


**Rotated Till**



Section 7b

— 2003 — 2006 — 2013 — 2014

**Immediately Prior to 2nd Kame Terrace Failure P2 (+/- 13,450 YBP)**






# Section 7b

— 2003 — 2006 — 2013 — 2014

## P2 Kame Terrace Failure (+/- 13,550 YBP)





Section 7b

2003

2006

2013

# P2 Headwall Collapse (+/- 13,550 YBP)

Whitman Bench

Initial Mid-Slope Bench

Rollins Creek

500

2000


2500

3000

3500

4000

4500







**Whitman Bench**

**2006 LIDAR**

**Mid-Slope Bench**

0 250 500 750 ft





**Old Surface of Rupture at  
Base of Remaining  
Mid-Slope Bench Block,  
West Margin**







**2013 LiDAR**

**Surface of Rupture  
At base of Mid-Slope Bench**

0 250 500 750 ft






**4/6/2014 LiDAR**

**2014 Surface of Rupture  
Exposure in Gully**

**Surface of Rupture  
At base of Mid-Slope Bench**





**Surface of Rupture 2014 Failure**

**Fine-Grained Glacio-Lacustrine**

**Bear Lake Sand**






**Whitman bench**

**Mid-Slope Bench**



**2006 Photo Courtesy Bucky Tart**






# Section 7b

— 2003 — 2006 — 2013 — 2016

## Ice Melt, Toe Erosion/Sliding (+/- 13,000 YBP)




00 2000 2500 3000 3500 4000 4500



# Section 7b

2003 2006 2013 2014

## Continued Erosion on Lower Slope (+/- 13,000 - 12,000 YBP)






Section 7b

2003 2006 2013 2014

**Relative Stability (+/- 12,000 YBP - Early 1900s)**







Section 7b

2003 2006 2013 2014

# N. Fork Impinges on Toe of Slope (Early 1900s - 1930s)











# Section 7b

— 2003 — 2006 — 2013 — 2014

## N. Fork Erodes Cover Over Bear Lake Sands (1940s - 1950s?)











# Section 7b

— 2003 — 2006 — 2013 — 2014

## De-stabilizing Lower Mid-Slope Bench (Mid 1960s) Steelhead Haven (Platted 1960)










# Hazel Slide January 7, 1967


48 Lots Flooded, 25 Cabins Destroyed

## Section 7b

2003 2006 2013 2014












# Section 7b

— 2003 — 2006 — 2013 — 2014



## Hazel Slide 1967 - 2006 N. Fork Moves N

































**Whitman Bench**

**Mid-Slope Bench**

**Surface of Rupture**

**Bear Lake Sand**

**2003 Photo Courtesy of Bucky Tart**










**Whitman bench**

**Mid-Slope Bench**



**2006 Photo Courtesy Bucky Tart**






Section 7b


— 2003 — 2006 — 2013 — 201

# Hazel Slide January 25, 2006 2006 LiDAR Topography Shown




500 2000 2500 3000 3500 4000 4500











2006 LIDAR

0 750 1500 ft









0 750 1500 ft



2013 LiDAR



Section 7b


2003

2006

2013


2014

# Initiation of March 22, 2014 Movement: M-1





# Piezometry within the Slide Mass





Section 7b


2003

2006

2013

2014

# Initiation of March 22, 2014 Movement: M-1






# Section 7b

— 2003 — 2006 — 2013 — 2014

## M2 (Mid-Slope Bench Failure Initiated)





Section 7b


2003

2006

2013

2014

# M3 Initiation, M2 Sliding on Saturated M1 Debris






Sec

2003

2006

# M-2 & M-3 Acceleration

M3 Accelerating on Steep Gradient, Leading Edge "in Compression"



1500

2000

2500

3000

3500


4000



Section 7b

— 2003 — 2006 — 2013 — 2014

# M-3 Maximum Velocity



M-3 Leading Edge Goes Into Tension

M-2 (Mid-Slope Bench) Accelerating on Low Slope

500 2000 2500 3000 3500 4000 4500 5000



# Section 7b


M-3 Trailing Edge Decelerating)

2003

2006

2013

## M-3 Leading Blocks on "Ballistic" Trajectory



1500

2000

2500

3000

3500

4000

4500




# Section 7b

M-3 Trailing Edge Decelerating)

— 2003 — 2006 — 2013 — 2014

## M-3 Leading Blocks Impact Slope Behind M-2 Remaining M-1 Debris Violently Mobilized



M-2 (Mid-Slope Bench) Reaches River

River "Turns Black and is Thrown Into the Air"

0 2000 2500 3000 3500 4000 4500 5000



Section 7b

M-3 Trailing Edge Decelerating)


2003

2006

2013

2014

# M-3 Leading Blocks Impact Trailing M-2 Trees Severe Disturbance of Impacting Blocks



1500 2000 2500 3000 3500 4000 4500 5000



Section 7b


2003

2006

2013

2014

# M-3 Central Blocks Fall into Void Vacated by M-2





# Section 7b


2003

2006

2013

2014

## M-3 Nearly Complete M-2 & Leading M-3 Blocks Continuing Southward




1500      2000      2500      3000      3500      4000      4500      5000



# Section 7b

— 2003 — 2006 — 2013 — 2014

## M-3 Nearly Complete M-2 & Leading M-3 Blocks Continuing Southward






Section 7b

— 2003 — 2006 — 2013 — 2014

# M-3 Complete M-2 Continuing Southward, Decelerating, Spreading and Stretching






# Section 7b

2003 2006 2013 2014

## M-2 Complete






Section 7b

— 2003 — 2006 — 2013 — 2014

**M-4 Headwall Collapse**







4/29/2014  
Photo Courtesy Tom Badger  
(Formerly WSDOT)



























4/1/14







2018



River Has Moved NW a Maximum of 175' in 4 Years



## IN SUMMARY:

- The Original Failure of the Mid-Slope Bench Dates to the End of the Last Ice Age
- Little Slope Movement Activity at the Site From +/-13,000 YBP Until the Early 1900s
- Significant Slope Movement Since the 1930s In Response to Erosion by NF
- There were Two Larger Events Prior to 2014, in 1967 and 2006.
- Slides of the last 100 Years Unloaded the Toe of the Mid-Slope Bench Failure P-2.
- There is no Evidence that Human Activity Contributed to the Oso Slide.
- The March 22, 2014 Event Unfolded in 4 Phases:
  - M-1 Minor Sliding of 2006 Slide Debris
  - M-2 Reactivation of Ice-Age P-2
  - M-3 Response of Previously Stable Portion of Kame Terrace (Whitman Bench)
  - M-4 Head Scarp Collapse.



# RECOMMENDATIONS:

- Resume Monitoring of the Current Slide Area (all Instrumentation has been Removed)  
This seems to be an inappropriate stick-your-head-in-the-sand approach
- Conduct Boots-on-the-Ground Assessments of Similar Geomorphic Features in Vicinity (DNR is apparently planning to do this in a limited fashion shortly).
- Form a Consortium of Stake Holders (Including Government Regulators, Tree Farmers, and Environmental Groups) to Devise Strategies to Address/Assess the Dominant Paradigm that "Logging Causes Landslides". This idea, which started in the 1930s or before, is counterproductive for all interests as it implies that everyone would be "safe but for logging." I realize that the rule-making process was structured somewhat similarly to this idea, but it did not involve actual investigations.
- No Worries for Oregonians of the same thing happening! Oregonians can instead worry about garden-variety non-glacial landslides (some bigger than Oso) and debris flows.